



## SAFETY ALERT 11-2025

REPORTING A DANGEROUS SITUATION/EVENT FROM WHICH WE CAN LEARN

### GENERAL INFORMATION


COMPANY NAME	BMN
LOCATION/ESTABLISHMENT	DC Etten-Leur
DATE	November 2025

### DESCRIPTION OF THE SITUATION(S)/EVENTS

Shortly after leaving the DC, the trailer came loose from the truck while taking a turn. The driver and colleagues immediately cordoned off the area and informed the proper authorities. Thanks to the quick action of the driver and colleagues involved, further consequences could be avoided and no personal injuries occurred. The trailer was picked up by a recovery company and delivered to the garage for technical inspection. The driver was able to finish his trip with another available truck.

Internal investigation has shown that the driver did all safety checks before the start of his ride and the night before the ride the combination was checked by two other colleagues. Fortunately, for this reason, we were able to rule out the possibility that the incident was caused by human error. Even more reason to emphasize the need to carry out these safety checks.

### RELEVANT PHOTOS OF THE SITUATION(S)/EVENT



### WHAT MEASURES CAN WE TAKE TO PREVENT A RECURRENCE OF THIS INCIDENT?

- Do your daily security checks before the start of your ride
- Be aware of the actions you perform during your work and check your surroundings
- Always report an unsafe situation (if possible via the Compass app) and take immediate measures.
- Check whether this situation also occurs in your location and, if necessary, take measures to ensure safety

Ask these three questions:

1. Can this accident be prevented at our location?
2. What systems are in place to prevent this type of accident at our site?
3. Are these systems applied?



Version: 1.0	Process owner: H&S	Print date: 06/11/2025
Version date: 17/03/2025	Functional manager: H&S Manager	page: 1/1