



SAFETY ALERT 12-2025

REPORTING A DANGEROUS SITUATION/EVENT FROM WHICH WE CAN LEARN

GENERAL INFORMATION


COMPANY NAME	BMN
LOCATION/ESTABLISHMENT	BMN Ede
DATE	November 2025

DESCRIPTION OF THE SITUATION(S)/EVENTS

Two employees were working on a sawing order. While sawing the 2nd or 3rd plate, it went wrong with the removal of the sawn part. Part of the plate unexpectedly fell on the foot of the colleague who was doing support work. Despite wearing safety shoes, the tip of the plate ended up behind the reinforcement of the shoe, leading to injury.

An annoying incident and yet it once again makes it clear that it is important that clear instructions, good communication and regular repetition of safety agreements are essential to prevent an incident like this in the future.

RELEVANT PHOTOS OF THE SITUATION(S)/EVENT



WHAT MEASURES CAN WE TAKE TO PREVENT A RECURRENCE OF THIS INCIDENT?

- Provide clear work instructions for sawing, supporting and removing sheet material and repeat them regularly
- Be aware of the actions you perform during your work and always wear the prescribed PPE
- Always report an unsafe situation (if possible via the Compass app) and take immediate measures.
- Check whether this situation also occurs in your location and, if necessary, take measures to ensure safety

Ask these three questions:

1. Can this accident be prevented at our location?
2. What systems are in place to prevent this type of accident at our site?
3. Are these systems actually applied?



Do you have questions about our Safety Alerts or do you want to know more?

Please contact the H&S department via hands@bmn.nl

Version: 1.0	Process owner: H&S	Print date: 02/12/2025
Version date: 17/03/2025	Functional manager: H&S Manager	page: 1/1

Uncontrolled version when printed For internal use only